VCI Packaging Guidelines

Do's and Don'ts for the proper use of VCI packaging to prevent rust on metal parts.



NO

Do not leave boxes of VCI poly or paper open.



YES

Replace unused sheets back into the box at the end of the shift.



NO

Do not handle unpainted parts with bare hands.



YES

Use gloves when handling bare metal parts.



NO

Parts must be completely covered. Cover all non-painted surfaces.



YES

Cover parts completely with VCI with logo facing outward.



NO

Do not leave VCI bag open. Close the bag.



YES

Roll or fold bag so VCI stays inside to protect the part. Close and seal box.



NO

Parts should not touch cardboard, corrugated boxes or wooden pallets.



YES

Secure properly packaged parts to pallet.

